

/院外薬局(Firm)/患者リスト

| Drive Family | Models Affected | Firmware Affected | Recommended Firmware Update | KB |
|---------------------------------|-----------------|----------------------------------|--|------------------------|
| Seagate Barracuda 7200.11 | ST31500341AS | not CCxx,LCxx | Brinks-4D8H-SD1B.ISO | 207957 |
| | ST31000333AS | | Brinks-3D6H-SD1B.ISO | |
| | ST3640323AS | | Brinks-2D4H-SD1B.ISO | |
| | ST3640623AS | | Brinks-2D4H-SD1B.ISO | |
| | ST3320613AS | | Brinks-1D2H-SD2B.ISO | |
| | ST3320813AS | | Brinks-1D2H-SD2B.ISO | |
| | ST3160813AS | | Brinks-1D1H-SD2B.ISO | |
| | ST3500320AS | SD15,SD16, SD17,SD18, SD19 | MooseDT-SD1A-2D-8-16-32MB. ISO | 207951 |
| | ST3500620AS | | (Please Contact) | |
| | ST3500820AS | | | |
| | ST3640330AS | | | |
| | ST3640530AS | | | |
| | ST3750330AS | | | |
| | ST3750630AS | | MooseDT-SD1A-3D4D-16-32M B.ISO | |
| ST31000340AS | | | | |
| Seagate Barracuda ES.2 | ST3250310NS | All | SN06 is the latest firmware | 207963 |
| | ST3500320NS | | | |
| | ST3750330NS | | | |
| | ST31000340NS | | | |
| DiamondMax 22 | STM3500320AS | MX15 (or higher) | In Validation | 207969 |
| | STM3750330AS | | | |
| | STM31000340AS | | | |
| | STM31000334AS | All | In Validation | 207975 |
| | STM3320614AS | | | |
| | STM3160813AS | | | |